

TUNE UPS			WHEELS		
5000030-1	Full Overhaul	\$475	5000544	Build Wheel	\$60
5000030	Standard Overhaul	\$250	5000508	True Wheel	\$15
			5000508-1	True Wheel with spoke replacemer	\$25
5001625	Tune-Up (Inc Parts Install)	\$85	5000465	Tire Repair / Install	\$10
5002438	Warranty Tune-up	\$0			
5000027	Std Tune	\$60	DRIVETRAIN		
5000027-1	Tune add brake bleed	\$10	5000449	Adjust Gears	\$20
5000027-2	Tune add install / grease bb	\$15	5000484	Replace / Clean Drivetrain	\$40
5000027-3	Tune add hub overhaul	\$15	5000108	Chain Repair / Install	\$10
5000027-4	Tune add headset grease / overhaul	\$15			
5000027-5	Tune add tube / tire install	\$5	BRAKES		
5000027-6	Tune add chainring install	\$10	5000386	Adjust Brake / Install pads	\$15
			5000387	Bleed Brake	\$20
5000672	Build bike from box new	\$100	5000387-2	Bleed Brake with line replacement	\$30
5000682	Build bike from box used (includes tune)	\$100	5000387-3	Overhaul Master Cylinder (incl Bleed)	\$40
5001611	Box Bike	\$40	5000387-4	Overhaul Caliper (incl Bleed)	\$40
5000553	Bike Fit	\$30	5000450	True Brake Rotor	\$10
FRAMES			SEAT POSTS		
5001966	Overhaul Pivot per pivot	\$30	5001309	Install Adj. Seat Post	\$25
5001014-1	Tap / Face BB Shell (on bare frame)	\$20	5001309-1	Overhaul Adj. Seat Post	\$40
5002338-1	Face / Ream Headtube (on bare frame)	\$20	5001309-2	Install Adj. Seat Post (purchased fi	\$10
5000387-5	Face Disc Brake Tabs	\$15			
			HUBS/H'SET/BB		
FORKS			5002381	Adjust Hub	\$10
5000918	Fork Service - Bath Oil / Install Main Seals	\$30	5000503	Overhaul Hub	\$20
5000918-1	Fork Service - Standard Overhaul	\$65	5001388	Install Headset	\$35
5000918-2	Fork Service - Add Damper Cartridge O'hai	\$60	5002338	Overhaul Headset	\$20
5000918-3	Fork Service - Add Travel Adjust Overhaul	\$60	5001014	Overhaul BB	\$20
5000918-4	Full Fork Service - all of the above	\$165			
5001306	Install Fork	\$40	MISC		
			5002353	Install Fenders	\$15
SHOCKS			5002466	Install Bar Tape	\$15
5001385	Overhaul Air Sleeve	\$30	5002480	Install Computer	\$15
5001385-1	Overhaul Air Shock Damper (incl a/s serv)	\$75	5000482	Install Rack	\$15
5001385-2	Overhaul Air Shock Full (incl a/s serv)	\$100	5000483	Pedal Overhaul (per pedal)	\$20
5001385-3	Overhaul Coil Shock Damper	\$80			
5001385-4	Overhaul Coil Shock Full	\$120	5000476	General Repair	
5001967	Install DU Bushing	\$10			

*Note - service rates are guidelines and may vary on any individual repair